

AHERA - ASBESTOS RE-INSPECTION OF ACM & PACM

S. KINGSTOWN HIGH SCHOOL
SOUTH KINGSTON SCHOOL DEPARTMENT

REINSPECTION DATE: FEBRUARY 28, 2018
ORIGINAL BLDG - 1956
ADDITION - 1996

		INSPECTION FINDINGS FOR PACM									Initials of Surveillance Inspector					
		Type and Quantity of PACM			Response Action											
Location of ACBM	Floor	TSI FITTINGS & LAGGING	MISC	PLASTER WALL MATERIAL	ACM	FRIABLE	DAMAGED	PHYSICAL ACCESS.	HAZARD ASSESS.	RESPONSE	Comments / Notes	6 MONTH SURVEILLANCES				
		TSI		SURFACE								8/18	2/19	8/19	2/20	8/20
HOMOGENEOUS AREA		TSI		SURFACE												
TUNNELS	B	400+ L.F.			A	N	N	5	2	M8		N/C	N/C	N/C		
CORRIDOR @ LIBRARY	2	X			A	N	N	5	2	M8	ABOVE SUSPENDED CEILINGS	N/C	N/C	N/C		
AUDITORIUM LOBBY	2	X			A	N	N	5	2	M8	ABOVE SUSPENDED CEILINGS	N/C	N/C	N/C		
MUSIC CORRIDOR	2	X			A	N	N	5	2	M8	ABOVE SUSPENDED CEILINGS	N/C	N/C	N/C		
TANK ROOM & ADJOINING JANITOR OFFICE	B		NON ACM		N						12" WALL TILES AND GLUE DOBBS DO NOT CONTAIN ASBESTOS [4/7/15]					
ORIGINAL BUILDING CLASSROOMS, OFFICES & BATHROOMS	ALL			3,000+ S.F.	A	N	N	5	2	M8	ORIGINAL BUILDING - PLASTER WALLS & PLASTER CEILINGS ABOVE SUSPENDED CEILINGS ARE ASSUMED TO CONTAIN ASBESTOS.	N/C	N/C	N/C		
STORAGE ROOM @ BOILER ROOM		80 L.F.			A	N	N	5	2	M8		N/C	N/C	N/C		
P.E. STORAGE [UPPER LEVEL]				1800 S.F.	A	N	N	5	2	M8		N/C	N/C	N/C		
ORIGINAL BLDG. - THROUGHOUT BLDG ABOVE CEILINGS		300+ FITTINGS			A	N	N	5	2	M8		N/C	N/C	N/C		
ORIGINAL BLDG. - THROUGHOUT WINDOW CAULK & GLAZE			3,000 L.F.		A	N	N	5	2	M8		N/C	N/C	N/C		
ORIGINAL BLDG. - THROUGHOUT - DOOR CORE			200+		A	N	N	5	2	M8		N/C	N/C	N/C		

Code: N = NO; Y = YES; T = THERMAL; S = SURFACING; M = MISCELLANEOUS
N/C = NO CHANGE; R = REPAIRED; D = DAMAGED

7/31/14 - STAIRWAY FLOOR TILE/MASTIC AT LANDINGS AND STAIR TREADS ABATED @ #316, ELEVATOR, BOYS LAV AND #331, STAIRWAY MASTIC @ 332A WAS NOT ABATED.