



Loss Prevention Report

The Hartford Steam Boiler Inspection and Insurance Company

Insured: Rhode Island Interlocal Risk Management Trust	Client Company: AIG - PEP/IP and TPIP
Location: South Kingstown High School 215 Columbia St Wakefield, RI 02879	Policy No.: 4DU0QYS80
Conferred With: Russell Hill	HSB ID No.: BN-1002532
Service Date: July 20, 2020	HSB Location No.: 71964
	HSB Representative: Bob Voisinet

Inspection Summary

The purpose of this visit to your facility was to conduct follow-up loss prevention and jurisdictional inspections of insured equipment. Jurisdictional inspections are required for the issuance or renewal of the Certificates of Operation.

Recommendations remain outstanding, and are listed below in this report. The State Certificates of Operation have not been recommended, pending completion of the Code recommendations. Please be advised that state law requires that all Code recommendations be completed prior to equipment operation.



Rhode Island Interlocal Risk Management Trust
July 20, 2020
Page 2

Recommendations

Code Recommendations

Violations of local codes that are required to be corrected by law.

Recommendation No.:	Equipment ID:	Initial/Follow-up:	Recommendation Status:
B-04-11-02-01/OP-01	RI037412/HW Stg Tank	Follow-up	Open

Equipment

Kitchen hot water supply storage tank located in gas boiler room.

Condition

The manufacturers identification label (Stamping) on the hot water storage tank in the gas boiler room is covered with insulation. It cannot be determined if this object was constructed to the requirements of the Jurisdiction. Jurisdictional requirements are that the manufacturers identification label or ASME stamping must be visible.

Recommendation

Locate and make visible the hot water storage tank manufacturers label / ASME stamping.

Status: August 10, 2005 - The manufacturers identification label or stamping has not been located to date. This recommendation remains open.

Status: December 1, 2006 - The manufacturers identification label or stamping has not been located to date. This recommendation remains open.

Status: August 17, 2006 - This recommendation was not addressed during this inspection visit. This recommendation remains open.

Status: August 22, 2008 - The manufacturers identification label or stamping has not been located to date. This recommendation remains open.

Status: July 29, 2010 - The manufacturers identification label or stamping has not been located to date. This recommendation remains open.

Status: August 30, 2010 - This recommendation was not addressed during this inspection visit and remains open.

Status: August 6, 2012 - This recommendation has not been addressed and remains open.

Status: July 26, 2013 - A discussion with Mr. Rafferty revealed that this recommendation has not been addressed. This recommendation remains open.

This report does not purport to set forth all hazards nor to indicate that other hazards do not exist. By issuing this report, neither the Company nor any of its employees makes any warranty, express or implied, concerning the contents of this report. Furthermore, neither the Company nor any of its employees shall be liable in any manner (other than liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect.



Rhode Island Interlocal Risk Management Trust
July 20, 2020
Page 3

Status: August 4, 2014 - The manufacturers identification label or stamping has not been located to date. This recommendation remains open.

Status: August 4, 2016 - No action has been taken. The ASME stamping has not been located. I explained the requirement and necessity of locating the tank data plate to Mr. Fillion along with the most likely location where it would be found on the tank. This recommendation continues to remain open.

Status: November 8, 2016 - Some areas of insulation have been open to locate nameplate, but still not found. I suggested researching installation plans and contacting installing contractor for assistance.

Status: July 11, 2018 - The above referenced manufacturers ASME identification label (Stamping) on the hot water storage tank has still not been made visible for inspection. This Jurisdictional operating certificate requirement was explained to Facilities Director Russell Hill.

Status: July 24, 2019 - The above referenced manufacturers ASME identification label (Stamping) on the hot water storage tank has still not been made visible for inspection. Facilities Director Russell Hill explained that they are removing a section of insulation at a time to try and locate it as well as not having to completely remove all insulation and to preserve the insulation so each piece can be put back in place. This Code recommendation remains open.

Status: July 20, 2020 - A discussion with Facilities Director Russell Hill indicated the tank stamping was not identified. He is looking at options of replacing the tank. This recommendation remains open.

Photos
No visible ASME data plate



This report does not purport to set forth all hazards nor to indicate that other hazards do not exist. By issuing this report, neither the Company nor any of its employees makes any warranty, express or implied, concerning the contents of this report. Furthermore, neither the Company nor any of its employees shall be liable in any manner (other than liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect.



Rhode Island Interlocal Risk Management Trust
July 20, 2020
Page 4

Comments

Thank you for the cooperation received during this inspection. Please contact the Customer Service Center at 1-800-333-4677 with any questions or concerns regarding this report, and to schedule a final inspection pending resolution of the code recommendations.

Please visit Equipment Operation and Efficiency: Schools K-12 for simple steps you can take to save energy and keep the equipment you depend on running smoothly. Click here:
http://www.hsb.com/HSBExt/APIP_Schools_Kto12-Operations.aspx.

HSB not only provides equipment breakdown insurance and loss prevention services, but is also committed to helping its customers save money and resources by identifying equipment energy efficiency opportunities. To learn more about potentially saving money, how to improve operation of key equipment and making informed energy decisions for your business visit our **HSB Efficiency First™** Website. This self-help site has access to tools and resources that could improve your bottom line!

HSB Efficiency First™
https://hsbefficiencyfirst.energysavvy.com/business/?src_code=hsblpr17

This report does not purport to set forth all hazards nor to indicate that other hazards do not exist. By issuing this report, neither the Company nor any of its employees makes any warranty, express or implied, concerning the contents of this report. Furthermore, neither the Company nor any of its employees shall be liable in any manner (other than liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect.

P.O. Box 61509 • King of Prussia, Pennsylvania 19406-0909
Tel: 1-800-333-4677 • Fax (800) 801-3199
www.hsb.com



POL - 1002532

LOC - 71964

THIS REPORT HAS BEEN DISTRIBUTED TO:

RUSSELL HILL
SOUTH KINGSTOWN HIGH SCHOOL
ELECTRONIC COPY
RHILL@SKSD-RI.NET
COPIES = 00

BRYAN MURRAY
RHODE ISLAND INTERLOCAL RISK MANAGEMENT TRUST
ELECTRONIC COPY
BMURRAY@RITRUST.COM
COPIES = 00

BRAD WEAVER
RHODE ISLAND INTERLOCAL RISK MANAGEMENT TRUST
ELECTRONIC COPY
BWEAVER@RITRUST.COM
COPIES = 00

F. GARCIA
ALLIANT
ELECTRONIC COPY
FGARCIA@ALLIANT.COM
COPIES = 00

J. SWARBRICK
ALLIANT
ELECTRONIC COPY
JJSWARBRICK@ALLIANT.COM
COPIES = 00

KEN FOGARTY
RHODE ISLAND INTERLOCAL RISK MANAGEMENT TRUST
ELECTRONIC COPY
KFOGARTY@RITRUST.COM
COPIES = 00

LORI BANNO
RHODE ISLAND INTERLOCAL RISK MANAGEMENT TRUST
ELECTRONIC COPY
LBANNO@RITRUST.COM
COPIES = 00

tc

This report does not purport to set forth all hazards nor to indicate that other hazards do not exist. By issuing this report, neither the Company nor any of its employees makes any warranty, express or implied, concerning the contents of this report. Furthermore, neither the Company nor any of its employees shall be liable in any manner (other than liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect.