

# AHERA - ASBESTOS RE-INSPECTION OF ACM & PACM

**PEACEDALE ELEMENTARY SCHOOL**  
 SOUTH KINGSTON SCHOOL DEPARTMENT

REINSPECTION DATE: FEBRUARY 28, 2018  
 SCHOOL WAS COMPLETELY REBUILT IN 1993

		INSPECTION FINDINGS						Initials of Surveillance Inspector									
		Type and Quantity	Response Action														
Location of ACBM	Floor	PLASTER WALL MATERIAL	FRIABLE	DAMAGED	ACCESS	POTENT. DAMAGE	RESPONSE	Comments / Notes									
HOMOGENEOUS AREA		SURFACE						6 MONTH SURVEILLANCES									
								8/18	2/19	8/19	2/20	8/20					
ORIGINAL BUILDING	B-1	PL	N	N	Y	X	S8	ORIGINAL BUILDING - PLASTER WALLS & PLASTER CEILINGS ABOVE SUSPENDED CEILINGS ARE ASSUMED TO CONTAIN ASBESTOS.					N/C	N/C	N/C		

Code: N = NO; Y = YES; T = THERMAL; S = SURFACING; M = MISCELLANEOUS  
 N/C = NO CHANGE; R = REPAIRED; D = DAMAGED