

# AHERA - ASBESTOS RE-INSPECTION OF ACM & PACM

## WAKEFIELD ELEMENTARY SCHOOL

SOUTH KINGSTON SCHOOL DEPARTMENT

REINSPECTION DATE: FEBRUARY 28, 2018

ORIGINAL BLDG. BUILT IN 1964

ADDITION ADDED IN 1990

		INSPECTION FINDINGS			Response Action						Initials of Surveillance Inspector					
		Type and Quantity														
Location of ACBM	Floor	ACM FITTINGS	MISC	GYPSUM / JOINT COMPOUND WALL MATERIAL	ACM	FRIABLE	DAMAGED	PHYSICAL ACCESS.	HAZARD ASSESS.	RESPONSE	Comments / Notes	6 MONTH SURVEILLANCES				
												8/18	2/19	8/19	2/20	8/20
<b>HOMOGENEOUS AREA</b>		<b>TSI</b>		<b>SURFACE</b>												
ORIGINAL BUILDING CLASSROOMS, OFFICES & BATHROOMS	1			3,000+ S.F.	N	N	N	Y	Y	S8	ORIGINAL BUILDING - PLASTER WALLS & PLASTER CEILINGS ABOVE SUSPENDED CEILINGS ARE ASSUMED TO CONTAIN ASBESTOS.	N/C	N/C	N/C		
STAGE	1	20			Y	N	N	Y	Y	T7		N/C	N/C	N/C		
CUSTODIAL OFFICE	1	12			Y	N	N	Y	Y	T7		N/C	N/C	N/C		
ASSUMED ABOVE SUSPENDED CEILINGS	1	50+			Y	N	N	N	Y	T7		N/C	N/C	N/C		
PE OFFICE	1	8			Y	N	N	Y	Y	T7		N/C	N/C	N/C		
KITCHEN	1	1			Y	N	N	5	2	T8		N/C	N/C	N/C		
PE STORAGE / KILN	1	12			Y	N	N	Y	Y	T7		N/C	N/C	N/C		
ELECTRICAL ROOM	1	20			Y	N	N	Y	Y	T7		N/C	N/C	N/C		
READING ROOM	1	10			Y	N	N	Y	Y	T7		N/C	N/C	N/C		
ORIGINAL BLDG. THROUGHOUT WINDOW CAULK & GLAZE			2000+ L.F.		A	N	N	5	2	M8		N/C	N/C	N/C		
ORIGINAL BLDG. - THROUGHOUT - DOOR CORE			60+		A	N	N	5	2	M8		N/C	N/C	N/C		

Code: N = NO; Y = YES; T = THERMAL; S = SURFACING; M = MISCELLANEOUS  
 N/C = NO CHANGE; R = REPAIRED; D = DAMAGED